

## MEMORANDUM

TO: Donald C. Norseth, Distribution Engineer

FROM: Grant Twitchell, Water Commissioner

RE: Bad Meter List, Beryl Enterprise System

Date: December 6, 1977

<u>Acct. #</u>	<u>Name of User/Operator</u>	<u>Remarks</u>
1	Adams Bros. c/o Sherwin Adams Enterprise, Utah	Meter reading erratic
9a	Ivan Barlow Enterprise, Utah	Meter reading erratic
11	S. P. Lipoma Co. c/o Bob Helquist Beryl, Utah	Meter not working on west well
14b	Leon Bowler Enterprise, Utah	Meter not working on Town well
16	Sherwood Bracken Enterprise, Utah	Meter reading erratic on No. Zukerman well
21	Christensen Bros. Newcastle, Utah	Meter not working on west well
21	Christensen Bros.	No meter on new hot well
31b	George Gardner Beryl, Utah	Meter not working
34c	Elmo & Gary Farnsworth Enterprise, Utah	Meter not working on south well
38a	Darwin Hulet Newcastle, Utah	Meter not working on well in pump hut
46	Jack E. Moyle Enterprise, Utah	Meter not working on well #1
51	H. Wayne Holt Beryl, Utah	Meter not working on west well
75	S. P. Lipoma Co. Beryl, Utah	Meter not working on N. Sec. 30 well
83	Bekins Bar V Newcastle, Utah	Meter not working on NW Sec. 11 well
88	Willard Randall Enterprise, Utah	Meters reading erratic on well by pond and well in W Sec. 1

106	Heber Staheli Enterprise, Utah	Meter not working on west well
108a	Harry Randall Enterprise, Utah	Meter not working
114	Fenton Terry Enterprise, Utah	Meters not working on both wells
147	Trusten Hart c/o Melvin Gardner Newcastle, Utah	Meter not working
149	Richard Flinspach Modena, Utah	Meter not working
154	Thomas Buhl 5450 The Toledo Long Beach, CA 90803	Meter not working on both wells

cc: Gerald W. Stoker, Area Engineer